

Local Notices to Mariners

LNTM No.	004/2015
Subject	Guernsey – Little Russel to Great Banks - Depths

Issues have been identified with the **December 2014** publication of charts **3140, 807 & 808**. Below is a list of the significant shoal or controlling depths that should be reinserted along the main leading lines and in the approaches to the port:

Depths to be reinserted on chart 3140

5.9m -controlling depth in port entrance. 49-27.351N 2-31.516W
2.1m rock - previously shoalest depth on the lead. 49-27.960N 2-30.665W
2.5m - Trois Grunes. 49-28.168N 2-30.398W
0.9m – Ferico. 49-27.147N 2-31.318W
4.9m – shoalest depth on the portion of Great Bank on chart. 49-26.920N 2-30.179W

Depths to be reinserted on charts 807 and 808

6.1m. - 49-29.34N 2-28.50W
Drying – 0.6m - drying height of rock close NE of Roustel beacon - 49-29.26N 2-28.71W
4m – Grune au Rouge. 49-28.46N 2-29.75W
2.5m – Trois Grunes. 49-28.17N 2-30.39W
Drying -1.5m – Foutu rock. 49-28.12N 2-29.25W
Drying -1.5 – Fourquies of Belle Greve rock. 49-28.06N 2-31.01W
2.1m – previously shoalest depth on the lead. 49-27.96N 2-30.66W
4.9m - near northern end of Great Bank. 49-26.93N 2-30.17W
4m - shoalest depth on The Great Bank.. 49-26.21N 2-30.50W
Drying -1.2 - Lower Heads Rock. 49-26.09N 2-28.69W
Drying -2.1m – Gabrielle Rock. 49-25.83N 2-31.58W

Elsewhere in the area, behind the 5 metre contour, depths over off lying shoals and rocks may be up to 2 metres less than charted.

Mariners are advised to navigate with caution in the area. New editions of charts 807, 808 and 3140 will be published as a matter of urgency when these issues are resolved.

Charts affected 3140, 807, 808 (December 2014)

Guernsey Harbours
St Julian's Emplacement
St Peter Port
Guernsey

www.guernseyharbours.gov.gg

Captain Chad Murray
Harbour Master