

Local Notices to Mariners

LNTM No.	010/2022
Subject	Roustel Beacon – Out of Position & Extinguished

Roustel Beacon (A1552) (49 29.23N 002 28.79W) is currently out of position with the light extinguished.

An **exclusion zone of 50m** has been established around the rock as the displaced structure is unstable.

